

MPC-25



McCAULEY™

Governor Operator/Owner Manual

TACH

DESCRIPTION OF WORK PERFORMED

SIGNATURE

Disassembled (1) ~~propeller~~ m/n D2A34C58-N s/n 722201
repaired red dye leak c/w s/b 227B, s/l 76-19, 78-2, 91-5A,
98-8B, 07-12. Assembled, oil filled, painted tips and
balanced. Bld. Dwg.# S-90AT-8 #1) K97307YS #2) C27399YS.

H & H Propeller Service, Inc.

3439 S. Aviation Dr.

Burlington, NC 27215

1-800-334-6437

FAA Repair Station PS4R451M



Governor Installation Record

Date Installed	Notes	Authorized Signature	Date Removed
12/20/14	INSTALLED PROPELLER M/N OZA34058 - A/SN722201		
A/c Tech 3377.0	AFTER H+H PROPELLER OH FOR RED DYE LEAK, OK,		
	Alfardo Guala 2010409 AMP.		
12/15/15 3384 hA 7.0504	Inspected Prop for an 100 hr Inspection Per FAR 43 App D. and found in Airworthy condition Robert W. C. C.		

2164P 1931575

Governor Installation Record

Date
Installed

Notes

Authorized
Signature

Date
Removed

MPC-25
MARCH 2004