

88A ✓

Propeller Owner's Manual & Log Book

Installation
Operation
Service

for **HARTZELL PROPELLERS**
D.O.A. - F.A.A. Approved Manual 115 M

"Compact" Models HC-C (2, 3, 4) Y; HC-E (2,3) Y;
HC-F (2, 3, 4) Y; HC-G (2,3) Y; (P) HC-L3Y;
BHC-L2Y; HC-H3Y; (P) HC-J3Y; BHC-J2Y; ()
HC-12Y; and () HC-M2Y - Constant Speed and
Feathering

This Manual Will Be Periodically Updated.

October 1980



Hartzell Propeller Products

TRW Aircraft
Components Group
P.O. Box 1458
1800 Covington Avenue
Piqua, Ohio 45356
513-778-4200
Telex 288039

PROPELLER MAINTENANCE RECORD

LEFT ENGINE

Hub Model HC-C2YK-1BF

Blade Design F.8477-4

Diameter _____

Hub Ser. No. CH-27773

Blade Ser. Nos. _____

No. 1 F61590

No. 2 F61598

No. 3 _____

No. 4 _____

PITCH RANGE

High _____ Low _____

Feather _____ Reverse _____

Governor Model _____

RIGHT ENGINE

Hub Model _____

Blade Design _____

Diameter _____

Hub Ser. No. _____

Blade Ser. Nos. _____

No. 1 _____

No. 2 _____

No. 3 _____

No. 4 _____


PITCH RANGE

High _____ Low _____


Feather _____ Reverse _____

Governor Model _____

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
7/23/86	107.8	Prop Total Time in service 107.8. Inspected prop IAW a Annual inspection & found it to be in airworthy condition Dressed prop & replaced Fuel, bulkhead screws & rechecked. Prop is approved for return to service.	
		THREE WING AVIATION SIKORSKY AIRPORT STRATFORD, CT 06497 CASE 19-111	
		 (authorized signature)	
		W.O. No. <u>4044</u>	
9/19/86	146	Prop Blades Resonated by SENSOWICH CORP m w/o 82926 2nd/3rd Time with CASE 19-111	

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
1-23-90	564.41	REMOVED PRP FOR COMPLIANCE W/ AD 77-12-06. PRP TOTAL TIME IN SERVICE 564.41.	
		THREE WING MAINTENANCE CENTER, INC. SIKORSKY MEMORIAL AIRPORT STRATFORD, CT 06487	
		 (Authorized Signature)	
		WORK ORDER NO. 7718 CERTIFIED REPAIR STATION SL5R201N	
2-7-90		% AD 77-12-06 w/o 660311	
		THIS IS NOT AN OVERHAUL AND CANNOT BE CONSIDERED AS SUCH	
			

**FOR SENSENICH PROPELLER CO.
E. AIRPORT ROAD, P.O. BOX 5100
LANCASTER, PA 17601-0100
REPAIR STATION QV2R1231**

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

[illegible]

**DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS**

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
		DATE <u>10/30/52</u> TOTAL TIME <u>817.2</u>	
		certify this ^{Prop} Aircraft/Engine has been inspected in accordance with	
		a <u>100 Hr.</u> inspection and was	
		determined to be in airworthy condition.	
		Pertinent details of the inspection are on file at this agency under	
		work order No. <u>1021321</u>	
		SIGNED <u>Hugh Day</u>	
		HUNTING AIRCRAFT, INC.	
		FALCON FIELD AIRPORT	
		PEACHTREE CITY, GA	
		REPAIR STATION F1QR686K	

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

[illegible]

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

[illegible]

TRW